

Water samples tested in Department of Microbiology IGMC, Shimla

Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	Final report (72Hrs)	Reported on	Result
1289	14-Jul	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Public tap tibeti colony nabah		added	MPN= 40	Citrobacter Spp.		Unsatisfactory
1290			2	nabah supply nr. Shopping complex nabha		added	0	-		Excellent
1291			3	phagli tank		added	MPN= 13	Citrobacter Spp.		Unsatisfactory
1292			4	public tap nr sr. secondary school phagli		added	0	-		Excellent
1293			5	tube well no 2 untreated		NIL	MPN=180+	Klebsiella oxytoca		Unsatisfactory
1294			6	tube well no 2 treated		NIL	0	-		Excellent
1295			7	kasumpti reserrior		added	0	-		Excellent
1296			8	sanjauli reserrior		added	0	-		Excellent
1297	14-Jul	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	ridge tank shimla		added	0	-		in process
1298			2	mains field tank		added	0	-		in process
1299			3	bharari tank		added	0	-		in process
1300			4	dhalli tank		added	0	-		in process
1301			5	Chakkar tank		added	0	-		in process
1302			6	klollswood tank		added	0	-		in process
1303			7	Jakhu tank		added	0	-		in process
1304			8	vikasnagar tank		added	0	-		in process
1305			9	bowari shanan		NIL	0	-		in process
1306			10	handpump shanan		NIL	0	-		in process
1307			11	household 1 verma niwas shanan		NIL	0	-		in process
1308			12	household 2 verma cottage shanan		NIL	0	-		in process

1309	15-Jul	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Tara mata mandir tank	-	added	0	-	17-Jul	Excellent
1310			2	New Shimla Sec 3 tank(old)	-	added	MPN= 13	Klebsiella spp.	17-Jul	Unsatisfactory
1311			3	Public tap,Negi Market,Sec 3,New Shimla	-	added	0	-	17-Jul	Excellent
1312			4	New Shimla Sec 3,tank(new)	-	added	0	-	17-Jul	Excellent
1313			5	Tube well no 2(UV)Ashwani Khad(Untreated water)	-	NIL	MPN= 160	Citrobacter Spp.	17-Jul	Unsatisfactory
1314			6	Tube well no 2(UV)Ashwani Khad(treated water)	-	NIL	0	-	17-Jul	Excellent
1315			7	Kasumpati Reservoir	-	added	0	-	17-Jul	Excellent
1316			8	Sanjauli Reservoir	-	added	0	-	17-Jul	Excellent
1317	16-Jul	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	North Oak (OH) Tank	-	added	MPN=14	Citrobacter koserii	18-Jul	Unsatisfactory
1318			2	North Oak (UG) Tank	-	added	0	-	18-Jul	Excellent
1319			3	Public tap chaulanti Road, Sanjauli, near Crift zone	-	added	0	-	18-Jul	Excellent
1320			4	Public tap, sanjauli chowk	-	added	MPN=11	Citrobacter spp.	18-Jul	Unsatisfactory
1321			5	Sanjauli reservoir	-	added	0	-	18-Jul	Excellent
1322			6	Kasumpti Reservoir	-	added	0	-	18-Jul	Excellent
1323			7	Tubewell no.2 (uv) untreated , Ashwani Khad	-	Nil	MPN=180+	Klebsiella spp.	18-Jul	Unsatisfactory
1324			8	Tubewell no.2 (uv) treated , Ashwani khad	-	Nil	MPN=13	Pseudomonas spp.	18-Jul	Unsatisfactory
1325	17-Jul	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	sanjauli reservoir	-	added	MPN=180+	-	19-Jul	unsatisfactory
1326			2	Public tap Laxmi narayan mandir, sanjauli	-	added	MPN=5	-	19-Jul	in process
1327			3	Dhingoo mandir tank (upper)	-	added	MPN=11	-	19-Jul	in process
1328			4	Dhingoo mandir tank (lower)	-	added	MPN=4	-	19-Jul	in process
1329			5	Main supply ,tibetan colony, near malta niwas, Indu nagar	-	added	MPN=5	-	19-Jul	in process
1330			6	Tubewell no.2 (uv) untreated water , Ashwani khad	-	added	MPN=180	-	19-Jul	unsatisfactory
1331			7	tubewell no 2(uv) treated water, Ashwani khad	-	nil	MPN=5	-	19-Jul	in process
1332			8	Kasumpti Reservoir	-	added	0	-	19-Jul	Excellent

1333	16-Jul	Samples received under hepatitis project community medicine igmc(HP) shimla	1	Ridge tank shimla	-	added		-	18-Jul	Excellent
1334			2	mainsfield tank	-	added		-	18-Jul	Excellent
1335			3	bharari tank	-	added		-	18-Jul	Excellent
1336			4	Dhali tank	-	added		-	18-Jul	Excellent
1337			5	tavi tank	-	added		-	18-Jul	Excellent
1338			6	Knols wood tank	-	added		-	18-Jul	Excellent
1339			7	Jakhu tank	-	added		-	18-Jul	Excellent
1340			8	Vikasnagar tank	-	added		-	18-Jul	Excellent
1341			9	Hand pump lakkar bazar	-	nil	MPN=3	-	18-Jul	
1342			10	Primary school jakhu	-	nil		-	18-Jul	Excellent
1343			11	Bhnnie Bone building jakhu	-	nil		-	18-Jul	Excellent
1344			12	Titla house jakhu	-	nil		-	18-Jul	Excellent
1345	17-Jul	Samples received under hepatitis project community medicine igmc(HP) shimla	1	Ridge tank shimla	-	added		-	19-Jul	Excellent
1346			2	Mains field tank	-	added		-	19-Jul	Excellent
1347			3	Keleston tank	-	added		-	19-Jul	Excellent
1348			4	Dhali tank	-	added		-	19-Jul	Excellent
1349			5	Chakkar tank	-	added		-	19-Jul	Excellent
1350			6	Phase 3	-	added	MPN=1	-	19-Jul	
1351			7	Jakhu tank	-	added		-	19-Jul	Excellent
1352			8	Kusumpati tank	-	added		-	19-Jul	Excellent
1353			9	Hand pump chalaunthi	-	added	MPN=50	-	19-Jul	unsatisfactory
1354			10	Chau\launthi bavri	-	added	MPN=180+	-	19-Jul	unsatisfactory
1355			11	Simran house lower khalini	-	nil		-	19-Jul	Excellent
1356			12	Kaushal niwas lower khalini	-	nil		-	19-Jul	Excellent